

FIG. 1 (a)




FIG. 1 (b)




FIG. 2




FIG. 3




FIG. 4






FIG. 5 (a)



SUBSTRATE: VERTICAL ALIGNMENT  
 PROTRUSION: HORIZONTAL ALIGNMENT  
 ⇒ AMOUNT OF LIGHT LEAKAGE: SMALL

FIG. 5 (b)



SUBSTRATE: VERTICAL ALIGNMENT  
 PROTRUSION: VERTICAL ALIGNMENT  
 ⇒ AMOUNT OF LIGHT LEAKAGE: LARGE

FIG. 6 (a)




FIG. 6 (b)




FIG. 7




FIG. 8




FIG. 9




FIG. 10

